



Joint Tape FC8TS / Procedure


1. Peel a white cover of the joint tape up to a positioning guide.




2. Set one of the two separated tapes on a positioning guide, and stick the cover tape downward. (A row of feeding holes must be along a positioning guide.)




3. Set another one of separated tapes so as the section of both tapes are fit.



4. Bend the Joint Tape along a bending line and stick it on the back side of carrier tape.



5. Peel a positioning guide and a transparent tape



6. Finally, rub joint area of the Joint Tape in a finger.
All Completed.

Be sure a black tape sticks completely to the carrier tape.

